locate, communicate, accelerate

IN – Information Note

Topic:	**OBS421i-24, OBS421x-24 Information Note**
	UBX-15013632
Author:	pber
Date:	20-Apr-2015

1   Affected Products

The following products have been made available for ordering.

Product Name	Ordering Code	Type No	Remarks
OBS421i-24	CB-OBS421I-24-01B	CB-OBS421I-24-01B-00	Ordering code with previous version: CB-OBS421I-24
OBS421x-24	CB-OBS421X-24-01B	CB-OBS421X-24-01B-00	Ordering code with previous version: CB-OBS421X-24

2   Type of Change

[   ]   Hardware modification
[x]   Firmware update
[   ]   Documentation update

3   Description of Change

Firmware v5.3.1 is released together with an updated boot loader. To get modules with the new firmware and boot loader new ordering codes have been created. It's also possible to load the new firmware on existing modules, see the firmware download page for firmware release notes and the flash loader download page for instructions on how to update to the latest firmware.

4   Schedule

Firmware is available for download and evaluation.
Estimated first shipment date: 18-May-2015

5   Customer Impact and Recommended Action

Customers should verify the functionality of the new firmware before mass deployment on modules in running applications.

Modules with the new ordering code include an updated boot loader and should be verified to operate correctly in the customer specific application.